



*America's #1 Choice  
Quality & Reliability  
SINCE 1960*

## National Flight Services

# Twin Commander Services

*National Flight Services is the premier Twin Commander Service Center*, offering our customers a one-stop maintenance facility. With over 30 years experience as a Twin Commander Service Center, National Flight Services provides both airframe and TPE331 maintenance to make your Twin Commander fly higher, faster, and longer between maintenance visits, all at the least possible expense to our customers. Put the National Flight experience to work for you.



### LOCATIONS

**Toledo, Ohio**  
(Toledo Express Airport)  
Maintenance Facility:  
Phone 419.865.2311  
Fax 419.866.8322  
DSCR311D

Toledo Line Service:  
Phone 419.866.2995  
Fax 419.866.2999

Toledo Component Shop:  
Phone 419.866.5953  
Fax 419.867.4223

**Toronto, Ontario**  
Phone 905.450.6051  
Fax 905.450.7616  
AMO 364-91

**San Antonio, Texas**  
Phone 210.495.1411  
Fax 210.495.1415  
DSC2311D

**Lakeland, Florida**  
(Lakeland Linder Regional Airport)  
Phone 863.648.1648  
Fax 863.644.0757  
DSC4331D

#### TPE331 Engine Services

- Overhaul
- Hot Section Inspection
- Gear Box Inspection
- Compressor Refurbishment
- Woodward Fuel Control Modification
- All Major and Minor Repairs
- Extensive Rental Engine Pool
- Super One Conversion
- 24-Hour Tech Assistance
- Extensive Parts Inventory/AOG Services

#### Airframe Services

- All Airframe Inspections
- Aircraft Surveys
- Service Bulletin Compliance
- Spar Cap Replacement
- Pressurization Checks
- Window and Windshield Replacement
- Full Avionics Service and Install Available
- Paint and Interior Services Available

#### Twin Commander -10T Engine Conversion

- Prototyped in 1993, and debuting during the 1993 NBAA Show, the -10T Twin Commander transforms an aircraft that is legendary for its performance to an even better performing machine.
- 300+ KTAS
- Full Power to 16,000 feet (ISA)
- 3,500 FPM Initial Rate of Climb / Greater Than 2,000 FPM to FL 200
- 12 Minutes to FL290
- Increased Fuel Efficiencies
- Increased Range
- Increased Aircraft Value
- Reduced Hot Section Inspection Cost
- Factory Warranty on Turbine Components
- Replaceable 1st Stage Blades

FAA, EASA, Venezuelan, Brazilian, and Indonesian DGAC Authorized Repair Stations

**Honeywell**  
Authorized Service Center



**TWIN COMMANDER**  
AIRCRAFT LLC

[www.nationalflight.com](http://www.nationalflight.com)  
Toll Free: 800.669.2704