




*America's #1 Choice  
Quality & Reliability  
SINCE 1960*

## National Flight Services

# Fairchild Merlin and Metro Services

*Well-known in the industry for our expertise in Swearingen/  
Fairchild maintenance*, National Flight Services offers the convenience of one-stop-maintenance to our customers operating Merlin and Metro aircraft at multiple locations. Our factory trained Merlin/Metro experts specialize in the following services:

**Models Applicable:** SA26B (Merlin IIB), SA226 (Merlin III, IIIA, IIIB, IV, Metro I and Metro II), SA227 (Merlin IIIC, III-300, Metro III, and Metro 23)



### LOCATIONS

**Toledo, Ohio**  
(Toledo Express Airport)  
Maintenance Facility:  
Phone 419.865.2311  
Fax 419.866.8322  
DSCR311D

Toledo Line Service:  
Phone 419.866.2995  
Fax 419.866.2999

Toledo Component Shop:  
Phone 419.866.5953  
Fax 419.867.4223

**Toronto, Ontario**  
Phone 905.450.6051  
Fax 905.450.7616  
AMO 364-91

**San Antonio, Texas**  
Phone 210.495.1411  
Fax 210.495.1415  
DSC2311D

**Lakeland, Florida**  
(Lakeland Linder Regional Airport)  
Phone 863.648.1648  
Fax 863.644.0757  
DSC4331D

#### TPE331 Engine Services:

- Overhaul
- Hot Section Inspection
- Gear Box Inspection
- Compressor Refurbishment
- All Major and Minor Repairs
- Extensive Rental Engine Pool
- 24-Hour Tech Assistance
- Merlin IIB -6 Conversion
- Merlin -10 Conversion
- Extensive Parts Inventory/AOG Services

#### Airframe Services:

- Letter Check A thru D Inspections
- Aircraft Surveys
- Extensive Sheet Metal, Structural, and Corrosion Repairs
- AD and Service Bulletin Compliance
- Service of Both Rosemount and Conrac SAS systems

- Window and Windshield Replacement
- Deice Boot Repairs and Replacement
- Pressurization Repairs
- NiCad Battery Service and Installation
- Paint & Interior
- Avionics

#### Super One Conversion:

- Applies to the Merlin IIB
- Incorporates the Latest Compressor Configuration
- Improved Hot Day/High-Density Altitude With Same Fuel Burn
- Increased Air Speed at Higher Altitude With Same Fuel Burn
- Improved Single Engine Performance
- Less Thermal Distress - Increased Cooling
- Reduced Maintenance Costs at Scheduled Inspection Intervals

FAA, EASA, Venezuelan, Brazilian, and Indonesian DGAC Authorized Repair Stations

**Honeywell**

Authorized Service Center



**TWIN  
COMMANDER**  
AIRCRAFT LLC

www.nationalflight.com  
Toll Free: 800.669.2704